Form Rev.6 Effective: 08/31/99 WHS &		SETUP-DOC	TERPRISES, INC. UMENTATION ICO MACHINE		Page	1 of 2
Date April 19, 2001						
				Machine #	Mill # 8	
Setup Foreman		18391	Rev. C	Fixture Location	1-F	
				Operation #	2 of 2	
Quality Control	Precison Ent	erprises Job #	9803	Next Operation	Shipping	
Are all fixtures, tooling ,ect. From last job put away? Are all raw castings for the new job at the machine? Is Tooling preset? (If no, proceed without installing tools) Are Blueprints, fixtures, and inspection Equip. at the machine? Is the table and fixtures cleaned off and free of burrs?		Setup Ch	Are 3 Parts off and Is the setup Docum Is the production D	s been made and notes left Setup Documents filled out ents up to latest Rev. ? ocuments up to latest Rev?	?	
Are all fixtures installed and clamped down?			Is prouduction Card filled out to latest Rev.?			
Are all fixtures indicated?			Is the setup Book up to date with the latest Rev. ?			
Is the program in?			Are 3 Parts at Mach	ine and Q.C. notified?		
	MUS	T CHECK 3 PAI	RTS CONSECUTIVELY			

All Dimensions Must Be Within Target Range Before Quality Control Releases for Production

SPECIAL INFORMATION: SET-UP



SPECIAL INFORMATION: INSPECTION



## FILL IN GAGE NUMBERS USED TO CHECK PARTS. LETTERS COINCIDE WITH DIMENSIONS ON PROCEEDINGS PAGES.

.

1

А	Calipers	1st	2nd	N
в	Calipers		2nd	_ 0
С	.500 and .503 Gage Pins	1st	2nd	P
D	Height Gage	1st	2nd	Q
Е		1st	2nd	R
F		1st	2nd	s
G		1st _	2nd	т
н		1st _	2nd	U
I		1st	2nd	v
J	_	1st	2nd	w
κ	-	1st _	2nd	_ x
L	_	1st _	2nd	Y
М	_	1st _	2nd	_ Z

1st	2nd
1st	2nd